

n F S # 42-003-00032
 APC# 0
 ATP 1 00 - Outage let
 DTA 020128

January 28, 2002

Dr. Roger C. Westman
Department of Air Quality
Bureau of Air Pollution Control
301 Thirty-Ninth Street
Pittsburgh, PA 15201

U.S. Environmental Protection Agency
Region III
Air, Radiation & Toxics Division
1650 Arch Street
Philadelphia, PA 19103-2029
ATTN: James W. Hagedorn (3AT23)

Assistant Council
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745
ATTN: Ward Kelsey, Esq.

Department of Justice
Environmental and Natural Resource Division
Environmental Enforcement Section
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044
ATTN: David Street, Esq.

Subject: USS Reference Number: 02-0005
Sulfur Plant Incinerator Stack
USS Clairton Works

Gentlemen:

The attached form terminates the planned outage. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

R. R. Terza
General Manager
Clairton Works Raw Materials

NOTICE OF PLANNED OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. Planned Outage Number: 02-0005 Termination
2. Date & Time of Breakdown: Date: 01/15/02 Time: 0815 hours
3. Company Name: USX Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: Sulfur Plant Incinerator Stack
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: The spare sulfur plant incinerator stack will be unavailable for service for approximately 7 days to clean the piping from the Claus Plant to the incinerator stack.
8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
The spare incinerator stack will carry the load. No environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO₂ is an eye, nose, and throat irritant.
 - C. Amount of each type emitted (or likely to be emitted).
No environmental impact.
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).
The spare incinerator and stack carried the load.
10. Facility back in operation - Date: 01/25/02 Time: 1330 hours

Signature Coleen M. Davis Date 1/28/02
Coleen M. Davis
Environmental Control Engineer Phone: 233-1015